



NOTES:

1. STABLE TRENCH: UNDISTURBED SOIL OR COMPACTED TO 95% RC
UNSTABLE TRENCH: INSTALL ROCK BALLAST AND GEOTEXTILE FILTER FABRIC AS SHOWN

NAPA SANITATION DISTRICT



TITLE

RECYCLED WATER
TRENCH SECTION

DATE: MAY 2012

CHECKED BY: MW

APPROVED BY: TH

SCALE: NONE

DRAWING NO.

RW-4