



**NOTES:**

1. STABLE TRENCH: UNDISTURBED SOIL OR COMPACTED TO 95% RC  
UNSTABLE TRENCH: INSTALL ROCK BALLAST AND GEOTEXTILE FILTER FABRIC AS SHOWN

**NAPA SANITATION DISTRICT**



TITLE

RECYCLED WATER  
TRENCH SECTION

DATE: MAY 2012

CHECKED BY: MW

APPROVED BY: TH

SCALE: NONE

DRAWING NO.

RW-4